



Nestled in the heart of North London, this aging indoor swimming pool was in dire need of a comprehensive refurbishment. The existing steel liner pool had fallen into disrepair, plaqued by leaks and corrosion that rendered it unsafe and unsightly. Our team was commissioned to breathe new life into it, tasked with constructing a new reinforced concrete pool within the existing excavation.

From the onset, a meticulous demolition process was undertaken, carefully dismantling the deteriorating steel structure to make way for the new construction. Engineered to meet the highest standards, the reinforced concrete shell formed the foundation of the revitalised pool, ensuring structural integrity and longevity. A brand new filtration system was seamlessly integrated, guaranteeing perfect water quality and circulation for a relaxing swimming experience.

Elevating both functionality and aesthetics, a striking mosaic tile band was installed along the waterline, adding a touch of elegance and durability. The interior walls were coated with specialised waterproof coating, creating

